

**Transducer 24 VAC/DC, with intrinsically safe circuits for passive sensors in hazardous locations Zones 0, 1, 2, 20, 21, 22; with display**

**Serie EX-LINE**

**Type EXL-IMU-1**

## APPLICATION

The transducer is an associated intrinsically safe device for transmitting signals of passive sensors in hazardous areas into safe area's like Pt100, Ni1000, resistor sensors .... The sensor signals are transformed in signals (0...10 V- and 0...20 mA). The programming and adjustments of sensors are carried out on the device. Different sensor characteristics are integrated (see table 1).

Each module has a back light LCD display, which is used for programming, to indicate alarm signals and during operation. The display shows the actual value. A potential free contact is integrated for error recognition.

The measurement ranges of sensors and the output signals can be adjusted to any requirements of the system. For programming no tools are neccesary. The menu prompt is indicated over the display.



## TECHNICAL DATAS

Supply/Frequency	24 VAC/DC +/- 20 %, 50...60 Hz
Nominal current, Power consumption	100 mA, ca. 3.6 W, internal fuse without socket
Sensor input	Intrinsically safe circuit for passive sensors
Suitable sensors	see table 1
Sensor selection	accomplished by the customer, with menu prompt
Programming	direct on device, without additional tools
Sensor connection	2-3-4 wire on light blue terminals
Wire compensation	2-wire push button, 3- and 4 -wire automatically
Acceptable wire resistor	< 100 Ohm
Stability	stability < 0,2 % / year, temperature influence < 0,02 %/K, supply voltage influence < 0,01 %, setting time 0,5 sec. < 0,3 % end value
Accuracy	between out-, input and supply voltage
Galvanic isolation	measure range 16 Bit, outputs 12 Bit
A/D-converter	Voltage U and current I parallel available with tie point (GND)
Outputs	against short circuit and separate source voltage < 30 V
Outputs are protected	0...10 V- adjustable, burden < 500 Ω, influence < 0,05%
Voltage output U	0...20 mA adjustable, burden < 750 Ω, influence < 0,1%
Current output I	open circuit voltage < 26 V
Signals in alarm mode	increase or decrease selectable, 0 V-/0 mA or 10 V-/20 mA
Display	4 1/2 digits LCD-Display + special signs, back light
Buttons	status indication and actual value display (blank)
Failure / alarm indication	Push button for configuration/active mode, 5 buttons for setup, setup, menu prompt and parameter per display
Detection	over 1 potential free contact + output + display
Alarm indication 1 and 2	faulty sensor connected, short circuit, wire break
Failure- / alarm contact	over contact and analogue output UI, programmable
work-/storage temperature	Break contact, 24 V max. 1 A
-10...+ 50 °C / -40 ...+ 80 °C	
Electrical connection	Terminal, IP 20, max. 4 mm <sup>2</sup>
Housing	Plastic, IP 40, for Din Rail mounting acc. to EN 50022
Dimensions and weight	w x h x t 45 x 75 x 110 mm, ca. 190 g
Type of protection	II(1)GD [EEx ia] IIC,acc. to EN 50014/ EN 50020 associated intrinsically safe device
Protection class	PTB 03 ATEX 2092, for sensors in Zone 0, 1, 2, 20, 21, 22
CE 0158	94/9/EG (ATEX), 89/336/EG (EMC)
Included in price	<b>EXL-IMU-1 EEx-i Module with actual value display</b>
Installation area	Module in safe area, sensors in hazardous locations

II(1)GD [EEx ia] IIC  
Zone 0, 1, 2, 20, 21, 22  
PTB-approved acc. to  
ATEX



## CONNECTABLE SENSORS - TABLE 1

Sensor table	Range	Characteristics	unit
Pt 100 DIN	-200...+850°C	temp.-linear	°C
Pt 500/1000 DIN	-200...+850°C	temp.-linear	°C
Ni100/200/500/1000 DIN	-60...+180°C	temp.-linear	°C
LS-Ni 1000 (Siemens)	-30...+130°C	temp.-linear	°C
KP 250 (Kieback&Peter)	-50...+150°C	temp.-linear	°C
LF 20 (Honeywell Special 1)	-20...+100°C	temp.-linear	°C
Resistor without slider	0... 1 kΩ	resistor-linear	variable
in display figure 2	0... 10 kΩ		
Resistor with slider	0... 10 kΩ	resistor-linear	variable
in display figure 3	0... 1 kΩ		
DFK-.. (Special 2)	x...y Pa	angle linear	Pa
VFK-.. für VAV (Special 3)	x...y m/s	angle SQRT	m/s

## EEx-i circuits - TABLE 2

Nominal value	Maximal value on the terminal	
	II(1)GD [EEx ia] IIC	II(1)GD [EEx ia] IIB
Terminals	22-23-24-25	22-23-24-25
Voltage	U <sub>0</sub> 7,5 V	7,5 V
Current	I <sub>0</sub> 5 mA	5 mA
Power	P <sub>0</sub> 10 mW	10 mW
Capacity	C <sub>0</sub> 1,2 μF	4,9 μF
Inductivity	L <sub>0</sub> 10 mH	50 mH

**The maximum values must not be exceeded!**


Please check your external capacities and inductivities in acc. to the length of the cable and the method of installation.


## ATTENTION!

- For installation or maintenance official standards and rules must be adhered to!
- The energy of intrinsically safe circuits are below the level to start an explosion in the event of a spark.
- Intrinsic safe circuits must be installed with light blue coloured cables's and separate installed from non intrinsic safe circuits. Distance between terminals of intrinsic safe circuits and non intrinsic safe circuits must be a minimum of 50mm.
- The EXL-IMU-1 modules must be installed in the safe area. Sensors must be passive and potential free for use in hazardous locations in zone 0, 1 and 2 and 20, 21, 22.
- For applications in zone 20 and 21 you may use only sensors which apply the category 1D or 2D. In zone 0 only sensors which apply the category 1G
- Pay attention to the max values for sensors and wiring , listed in table 2.

## ELECTRICAL CONNECTION

### Temperature-/Humidity sensors Resistors linear, Potentiometer





Enter button  
Switch for Configuration  
to Active mode  
Multi function display for programming  
and actual value display  
Button for parameter selection  
Button for level selection

## Switching Configuration - Active

With the switching between "Active" = Operating modus and "Config" = Configuration mode, changes from the working function into the programming function. The switching from Active to Config is made by pushing one time the Config button (Conf in display) and then push the ENTER and Level up buttons at the same time.

After setup, start the active mode by pushing the config button.

Active → Config      Config → Active  
1. +   
2.

## Failure- and Alarm Indication


Different failure or alarm signals are indicated by contact and by display warnings. The following pictures show the most common errors and there cause.

### Display      Failure




Actual display value is flashing at low measuring range

Sensor error, actual value is lower than adjusted range or there is a short circuit fault at wiring. Contact is active - display shows Error Sensor Range




Display actual value is blinking at high measuring range

Sensor error, actual value is higher than adjusted range or the wiring is open. Contact is active - display shows Error Sensor Range



Value over or under measurement range  
Value is over or under adjusted range  
Display shows Error Range, Contact isn't active



Error status at wire compensation  
Wire resistors more than 100 Ohm aren't accepted.

## Notes to Sensors

For the following sensors there are separate datasheets for programming and setup available:  
Sensor type Ring balance, Potentiometer

Resistors with and without slider are different in the setup Level 01. Without slider is figure 2 + resistor value and with slider is figure 3 + resistor value.

Ring balance linear and root extraction (m/s) are different in Level 01 Sensor selection. Special 2 is linear for  $\Delta p$  and Special 3 for m/s

## Programming and Setup "Step by Step"

### TEMPERATURE SENSORS

Connection      Example: Pt100 DIN 2-wire  
Range      -20...100 °C  
Output      2-10 V, 4-20 mA  
Limit low      0°C  
Limit high      80°C

Active → Config      1. 1x      2. +

**Level      Function      Display      Select**

01	Select sensor type	Pt 100 DIN	
02	Select 2-3-4 wire	2-wire	
03	wire compensation	Pt 100 DIN 03 Wire Compensation	ENTER Sensor short circuit, ENTER
04	Select start of measuring range	- 20.0 °C	- 20 °C
05	Select end of measuring range	100 °C	100 °C
06	Select unit	The functions in Level 06 .. 09 are at temperature sensors preseted. Unit is °C, Decimal point is 0.1°C Begin and end measuring values depends on sensor type	
07	Select decimal point		
08	Select start of display value		
09	Select end of display value		
10	Output V/mA in fault conditions high or low	low	
11	Analogue output V start value	2.0 v	2.0 V
12	Analogue output V end value	10.0 v	10.0 V
13	Analogue output mA start value	4.0 mA	4.0 mA
14	Analogue output mA end value	20.0 mA	20.0 mA
15	Contact low limit value	0.0 °C	0.0°C
16	Contact low limit On/Off	On	
17	Contact high limit value	80.0°C	80.0°C
18	Contact high limit On/Off	On	
19	Actual value On/Off	Pt 100 DIN	Display On

Config → Active 1. 1x

### HUMIDITY SENSORS


Connection      Example: 1kOhm 4 wire  
Range      0...100 %  
Output      0-10 V, 0-20 mA  
Output in alarm situation      decrease to 0 V / 0 mA  
Limits      not applied

Active → Config      1. 1x      2. +

**Level      Function      Display      Select**

01	Select sensor type	0-1kΩ (2)	
02	Select 2-3-4 wire	4-wire	
03	wire compensation		This Level is automatically Passed
04	Select start of measuring range	0.0 Ω	0 Ohm
05	Select end of measuring range	1000.0 Ω	1000 Ohm
06	Select unit	%rF	%rF
07	Select decimal point	-- . --	-- . --
08	Select start of display value	0.00 %rF	0.00 %rF
09	Select end of display value	100.00 %rF	100.00 %rF
10	Output V/mA in fault conditions high or low	low	
11	Analogue output V start value	0.0 v	0.0 V
12	Analogue output V end value	10.0 v	10.0 V
13	Analogue output mA start value	0.0 mA	0.0 mA
14	Analogue output mA end value	20.0 mA	20.0 mA
15	Contact low limit value	0.00 %rF	0.00 %rF
16	Contact low limit On/Off	Off	
17	Contact high limit value	100.0 %rF	100.0 %rF
18	Contact high limit On/Off	Off	
19	Actual value On/Off	0-1kΩ (2)	Display On

Config → Active 1. 1x



Enter button  
Switch for Configuration  
to Active mode  
Multi function display for programming  
and actual value display  
Button for parameter selection  
Button for level selection

## Switching Configuration - Active

With the switching between "Active" = Operating mode and "Config" = Configuration mode, changes from the working function into the programming function. The switching from Active to Config is made by pushing the Config button (Conf in display) and then push the ENTER and Level up button at the same time. After setup, start the active mode by pushing the config button.


Active → Config  
1. +

Config → Active  
1. 1x

## Failure- and Alarm Signalisation


Different failure or alarm signal are indicated by contact and by display warnings. Following pictures shows the most indicated errors and there cause.

### Display Failure




Actual display value is flashing at low measuring range

Sensor error actual value is lower than adjusted range or there is a short circuit fault at wiring. Contact is active - display shows Error Sensor Range



Display actual value is blinking at high measuring range

Sensor error actual value is higher than adjusted range or the wiring is open. Contact is active - display shows Error Sensor Range




value over or under measurement range

Value is over or under adjusted range

Display shows Error Range, Contact isn't active



No value in display  
Select in Level 19 configuration mode  
Display On.



Error status at wire compensation  
Wire resistors more than 100 Ohm aren't accepted.

## Notes to Sensors

For the following sensors there are separate datasheets for programming and setup available:  
Sensor type Temperatur sensor, Humidity sensor

Resistors with and without slider are different in the setup Level 01. Without slider is figure 2 + resistor value and with slider is figure 3 + resistor value.

Ring balance linear and root extraction (m/s) are different in Level 01 Sensor selection. Special 2 is linear for  $\Delta p$  and Special 3 for m/s

## Programming and Setup "Step by Step"

### RING BALANCE ( $\Delta p$ , m/s)

Range Example: 0...40 Pa  
Output U/I 0...10 VDC/0...20 mA  
Output in alarm situation increase to 10 V / 20 mA  
Limits not applied

Active → Config 1. 1x 2. +

Level Function Display Select

01 Select sensor type Sensor 01 Special 2 (linear)

02 preselect no function

03 Calibration modus CAL  
03 Start Special 2  
CAL  
03 End Special 2  
ENTER (Start) draw the needle to 0Pa ENTER

04 preselect no function

05 preselect no function

06 Select unit Pa Pa  
06 Range Display Special 2

07 Select decimal point -- -- Pa -- --  
07 Range Display Special 2

08 Select start of display value 0.00 Pa 0.00  
08 Start Display Special 2

09 Select end of display value 40.00 Pa 40.00  
09 End Display Special 2

10 Output V7mA in fault conditions high or low  
10 Output Special 2

11 Analogue output V start value 0.00 0.0 V  
11 Start Output Special 2

12 Analogue output V end value 10.00 10.0 V  
12 End Output Special 2

13 Analogue output mA start value 0.00 0.0 mA  
13 Start Output Special 2

14 Analogue output mA end value 20.00 20.0 mA  
14 End Output Special 2

15 Contact low limit value 0.00 Pa 0.0  
15 Limit Special 2

16 Contact low limit On/Off Off  
16 Limit Special 2

17 Contact high limit value 40.00 Pa 40.0  
17 Limit Special 2

18 Contact high limit On/Off Off  
18 Limit Special 2

19 Actual value On/Off  
19 Display On Special 2



### POTENTIOMETER

Connection Example: 0-10 kOhm with slider  
Range 0...10 kOhm  
Output 0-10 V, /0-20 mA  
Output in alarm situation increase to 10 V / 20 mA  
Limits 1.000 kOhm, 9.000 kOhm

Active → Config 1. 1x 2. +

Level Function Display Select

01 Select sensor type Sensor 01 0-10 kOhm (3) 3 means slider connection

02 Select 2-3-4 wire 3 3  
02 Wire 0-10 kOhm 3

03 Wire compensation  
03 Start 0-10k 3  
03 Wire Compensation 0-10k 3  
push ENTER potentiometer turn left (low limit) push ENTER

04 Select begin of measuring range 0.000 kΩ 0.000 kOhm  
04 Start Range 0-10k 3

05 Select end of measuring range 10.000 kΩ 10.000 kOhm  
05 End Range 0-10k 3

06 Select unit kΩ kOhm  
06 Range Display 0-10k 3

07 Select decimal point -- -- kΩ -- --  
07 Range Display 0-10k 3

08 Select start of display value 0.000 kΩ 0.000 kOhm  
08 Start Display 0-10k 3

09 Select end of display value 10.000 kΩ 10.000 kOhm  
09 End Display 0-10k 3

10 Output V/M/A in fault conditions high or low  
10 Output 0-10k 3

11 Analogue output V start value 0.0 v 0.0 V  
11 Start Output 0-10k 3

12 Analogue output V end value 10.0 v 10.0 V  
12 End Output 0-10k 3

13 Analogue output mA start value 0.0 mA 0.0 mA  
13 Start Output 0-10k 3

14 Analogue output mA end value 20.0 mA 20.0 mA  
14 End Output 0-10k 3

15 Contact low limit value 1.000 kΩ 1.000 kOhm  
15 Limit 0-10k 3

16 Contact low limit On/Off On  
16 Limit 0-10k 3

17 Contact high limit value 9.000 kΩ 9.000 kOhm  
17 Limit 0-10k 3

18 Contact high limit On/Off On  
18 Limit 0-10k 3

19 Actual value On/Off  
19 Display On 0-10k 3